



INSTRUCTIONS FOR USE

SPECIAL LAUNDERING INSTRUCTIONS FOR UNCOATED COVERS

- 1. Washing Instructions** - Use mild non-bleach detergent suitable for nylon/polyester fabrics and follow manufacturer's instructions. Water temperature must not exceed 160° F.
- 2. Dry Instructions** - Air dry. If machine drying is necessary do not exceed a temperature of 250° F maximum and a time duration of two minutes maximum.
- 3. IRONING** - Do not put covers through flatwork ironers.

CAUTION: Washing or drying in excess of the above recommendations will reduce service life and performance of the product.

* Save this document for future application, load rating and/or safety reference.

US/Can: 1.800.992.1776
Corporate Headquarters (US): 1.570.825.2741
For Inquiries Outside of the U.S. and Canada, Visit www.metro.com/contactus

www.metro.com



L01-024 Rev.B
03/2016